

Appendix 2

Photographs taken of the pedestrian refuge at the junction of Winchester Road and Drapers Road



These photographs show that pedestrians can easily be injured by wing mirrors of passing vehicles due to the inadequate width of the carriageway.

